This Document contains information affecting the Na-

CENTRAL INTELLIGENCE AGENCY

INFORMAT	ION REPORT	25X1	This Document contains intrictional Defense of the United ing of Title 18, Sections 793 amended. Its transmission o to or receipt by an unautho by law. The reproduction of	States, within the mean- and 794, of the U.S. Code, as revelation of its contents rized person is prohibited
•		dewesen HF Lage in Tube Production 25X1	REPORT NO. DATE DISTR. NO. OF PAGES REQUIREMENT NO. REFERENCES	10 April 1953 1 25X1
SOURCE:	25X1X	RCE EVALUATIONS IN THIS REPORT THE APPRAISAL OF CONTENT IS TEI (FOR KEY SEE REVERSE)	ARE DEFINITIVE. NTATIVE.	

- 1. The percentage of spoilage in tube production has risen markedly of late in the Werk fuer Fernmeldewesen HF, in Berlin-Oberschoeneweide. It reached 60 to 70 percent on a number of days during February 1953. Carelessness in the manufacturing processes is to blame, according to a controller in the final control department where the tubes are tested, and this indifference goes back to the question of wages. A considerable part of the spoilage comes from the paste being applied too thickly to the cathodes, resulting in a short circuit between the cathode and the first grid. For this reason an entire week's production of the tube 6SH7 was scrapped.
- 2. Five of the electronic microscopes developed in the works have now been manufactured. Two are unfinished because material for the nozzle (Duese) is lacking. This requires a special kind of steel called V2A. The tolerance range of this microscope 's 5-100,000 mm.

			25X1
SECRET/			
	Ta		

	*						
STATE X ARMY	x NAVY	x AIR	X FBI	AEC	ORR Ev	<u>x</u>	
OTATE LAND							

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)